

Huawei Access Switch Alarm SOP for ALARM_6512

Node: Huawei-Access-Mumbai-MH-50 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM_6512

Description

This SOP outlines the procedures for diagnosing and resolving a critical alarm on Huawei Access Switch Node ID: Huawei-Access-Mumbai-MH-50, with Alarm Code ALARM_6512 and Severity Critical.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Bug	Medium
Environmental Factors	Low

Diagnostic Commands

```
display current-configuration | include ALARM_6512
show alarm 6512
display hardware
display version
```

Resolution Steps

- Step 1: {'Step': 'Power cycle the device', 'CLI_Command': 'quit system reboot'}
- Step 2: {'Step': 'Replace faulty hardware', 'CLI_Command': 'replace hw '}
- Step 3: {'Step': 'Upgrade software to latest version', 'CLI_Command': 'upgrade package '}
- Step 4: {'Step': 'Check environmental conditions and make adjustments as necessary', 'CLI_Command': 'display environment'}

Post-Check Verification

```
display current-configuration | include ALARM_6512
show alarm 6512
display hardware
display version
```