

Huawei Access Switch Alarm SOP: ALARM_2311

Node: Huawei-Access-Mumbai-MH-56 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_2311

Description

This SOP outlines the steps to diagnose, resolve, and verify the fix for Alarm Code ALARM_2311 on the Huawei Access Switch Node ID: Huawei-Access-Mumbai-MH-56.

Potential Root Causes

Cause	Probability
Incorrect configuration of the access switch	High
Hardware failure of the access switch	Low
Software issues with the access switch	Medium

Diagnostic Commands

```
display current-configuration
display fault-management alarm
display fault-management error
diag snmpwalk
```

Resolution Steps

- Step 1: {'Step': 'Check the access switch configuration for inconsistencies', 'Action': 'Run the command `display current-configuration` to verify the configuration'}
- Step 2: {'Step': 'Reset the access switch to its factory default settings', 'Action': 'Run the command `reset saved-configuration` to reset the access switch to its factory default settings'}
- Step 3: {'Step': 'Upgrade the access switch software to the latest version', 'Action': 'Run the command `upgrade system-software` to upgrade the access switch software'}

Post-Check Verification

```
display current-configuration
display fault-management alarm
display fault-management error
```