

Alarm Resolution SOP for Huawei Access Switch (Node ID: Huawei-Access-Mumbai-MH-56)

Node: Huawei-Access-Mumbai-MH-56 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_5877

Description

This SOP documents the steps to diagnose and resolve a warning-level alarm ALARM_5877 on Huawei Access Switch (Node ID: Huawei-Access-Mumbai-MH-56)

Potential Root Causes

Cause	Probability
Optical port issues, such as fiber cuts, loose connections, or optical module failure	High
Software configuration errors, such as incorrect port settings or misconfigured VLANs	Medium
Hardware failures, such as faulty cards or power supply issues	Low

Diagnostic Commands

```
display current-configuration | include optics
display interface brief | include error
display version | include sw-version
```

Resolution Steps

- Step 1: {'Step': 'Check optical port connections and ensure they are secure', 'Action': 'Verify physical connections and clean or replace if necessary'}
- Step 2: {'Step': 'Verify software configuration', 'Action': 'Compare configuration with expected settings and make corrections as needed'}
- Step 3: {'Step': 'Replace faulty hardware (if applicable)', 'Action': 'Replace optical modules, cards, or power supplies as necessary'}

Post-Check Verification

```
display interface brief | include error
display optics | include status
```