

Huawei Access Switch Mumbai Node (MH-56) Alarm Resolution SOP

Node: Huawei-Access-Mumbai-MH-56 | **Vendor:** Huawei | **Severity:** Major | **Alarm Code:** ALARM_6821

Description

This SOP is for resolving a Major Alarm on Huawei Access Switch Node ID: Huawei-Access-Mumbai-MH-56, with Alarm Code: ALARM_6821.

Potential Root Causes

Cause	Probability
Layer 2 Protocol Tunneling (L2PT) issue due to misconfiguration.	High
VLAN mismatch between trunk ports.	Medium
Switch software bug.	Low

Diagnostic Commands

```
display current-configuration system-view
display l2pt tunnel-information
display vlan vlan-id
display interface brief
```

Resolution Steps

Step 1: {'Step': 'Verify L2PT configuration and correct any misconfigurations.', 'Action': ["run the command 'display current-configuration system-view' to verify L2PT configuration.", 'correct any misconfigurations by running necessary commands.']}

Step 2: {'Step': 'Verify VLAN configuration on trunk ports and correct any mismatches.', 'Action': ["run the command 'display vlan vlan-id' to verify VLAN configuration on trunk ports.", 'correct any VLAN mismatches by running necessary commands.']}

Step 3: {'Step': 'Verify switch software version and apply necessary patches if required.', 'Action': ["run the command 'display version' to verify switch software version.", 'apply necessary patches to resolve software bug.']}

Post-Check Verification

```
display current-configuration system-view
display l2pt tunnel-information
```

```
display vlan vlan-id  
display interface brief  
ping test to verify connectivity
```