

Huawei Access Switch Alarm Resolution SOP: ALARM_4106

Node: Huawei-Access-Mumbai-MH-60 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_4106

Description

This SOP outlines the steps to diagnose and resolve the ALARM_4106 on Huawei Access Switch, Node ID: Huawei-Access-Mumbai-MH-60.

Potential Root Causes

Cause	Probability
High CPU utilization due to resource-intensive processes	High
Misconfigured VLANs or trunk interfaces	Medium
Hardware failure of interface or switch	Low

Diagnostic Commands

```
display cpu-resource
display vlan vlan-id
display interface interface-name
display system internal fault-info
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU utilization and resource usage', 'Action': 'Issue the command: display cpu-resource'}
- Step 2: {'Step': '2. Verify VLAN configuration and trunk interfaces', 'Action': 'Issue the command: display vlan vlan-id'}
- Step 3: {'Step': '3. Check interface and switch hardware status', 'Action': 'Issue the command: display interface interface-name'}
- Step 4: {'Step': '4. Clear system internal fault information (if any)', 'Action': 'Issue the command: clear system internal fault-info'}
- Step 5: {'Step': '5. Restart the switch (if hardware issues are suspected)', 'Action': 'Issue the command: reboot'}

Post-Check Verification

```
display cpu-resource  
display vlan vlan-id  
display interface interface-name  
display system internal fault-info
```