

Huawei Access Switch Alarm SOP: ALARM_5928

Node: Huawei-Access-Mumbai-MH-60 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM_5928

Description

Alarm ALARM_5928 on Huawei-Access-Mumbai-MH-60 indicates a critical software issue affecting the access switch.

Potential Root Causes

Cause	Probability
Software corruption due to faulty firmware upgrade	High
Hardware failure in the access switch	Medium
Misconfigured network settings	Low

Diagnostic Commands

```
display current-configuration | include ALARM_5928
show system internal error log
show interface status
show system resources
```

Resolution Steps

- Step 1: {'Step': 'Backup the current configuration', 'Description': 'Backup the current configuration to prevent data loss', 'CLI_Command': 'copy running-configuration backup:backup.cfg'}
- Step 2: {'Step': 'Revert to previous stable configuration', 'Description': 'Revert to the previous stable configuration to resolve the issue', 'CLI_Command': 'system revert to previous-configuration'}
- Step 3: {'Step': 'Update firmware to latest version', 'Description': 'Update the firmware to the latest version to resolve software issues', 'CLI_Command': 'system software install '}
- Step 4: {'Step': 'Verify and troubleshoot hardware issues', 'Description': 'Verify and troubleshoot hardware issues affecting the access switch', 'CLI_Command': 'show system internal error log'}

Post-Check Verification

```
display current-configuration | include ALARM_5928
show system internal error log
show interface status
show system resources
```