

Huawei-PE-Bangalore-KA-69 Minor Alarm Resolution SOP

Node: Huawei-PE-Bangalore-KA-69 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_3751

Description

This SOP outlines the steps to resolve the ALARM_3751 minor alarm on Huawei-PE-Bangalore-KA-69, a Huawei Provider Edge Router.

Potential Root Causes

Cause	Probability
Interface flapping	High
Routing protocol issues	Medium
Link issues (physical or logical)	Low

Diagnostic Commands

```
display current-connection
display interface brief
display ip routing-table
debug bgp
```

Resolution Steps

- Step 1: {'Step': '1. Check interface status and logs', 'Action': 'display interface brief and show log messages'}
- Step 2: {'Step': '2. Verify routing protocol configuration', 'Action': 'display ip routing-table and verify BGP configuration'}
- Step 3: {'Step': '3. Check link status and connectivity', 'Action': 'ping and traceroute to verify link connectivity'}
- Step 4: {'Step': '4. Clear any routing protocol adjacencies', 'Action': 'clear bgp '}
- Step 5: {'Step': '5. Verify and update BGP configuration if necessary', 'Action': 'display ip routing-table and verify BGP configuration'}

Post-Check Verification

```
display interface brief
display ip routing-table
```

show log messages