

Huawei Provider Edge Router Minor Alarm SOP: ALARM_8455

Node: Huawei-PE-Bangalore-KA-69 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_8455

Description

This SOP outlines the procedure for identifying and resolving a minor alarm on Huawei Provider Edge Router (Huawei-PE-Bangalore-KA-69) with Alarm Code ALARM_8455.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Interface Flapping	Medium
Routing Information Protocol (RIP) Loop	Low

Diagnostic Commands

```
display current-configuration
display cpu utilization
display interface status
display rip routing-table
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU Utilization', 'Action': "Use the command 'display cpu utilization' to check the current CPU utilization level.", 'CLI_Command': 'display cpu utilization'}
- Step 2: {'Step': '2. Check Interface Status', 'Action': "Use the command 'display interface status' to check the status of all interfaces.", 'CLI_Command': 'display interface status'}
- Step 3: {'Step': '3. Clear Interface Flapping', 'Action': "Clear the interface flapping issue by using the command 'clear interface '.", 'CLI_Command': 'clear interface GigabitEthernet 0/0/0'}
- Step 4: {'Step': '4. Check RIP Routing Table', 'Action': "Use the command 'display rip routing-table' to check the RIP routing table.", 'CLI_Command': 'display rip routing-table'}
- Step 5: {'Step': '5. Clear RIP Loop', 'Action': "Clear the RIP loop issue by using the command 'clear rip '.", 'CLI_Command': 'clear rip 10.10.10.1'}

Post-Check Verification

```
display current-configuration
```

```
display cpu utilization
display interface status
display rip routing-table
```