

Huawei Provider Edge Router (PE) Alarm Mitigation Procedure

Node: Huawei-PE-Bangalore-KA-71 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM_2637

Description

Alarm Code ALARM_2637 on Huawei-PE-Bangalore-KA-71: Critical Alarm -

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Fault	Medium
Misconfigured Routing Protocols	Low

Diagnostic Commands

```
show logbuffer | include ALARM_2637
show system internal alarm current-alarm
show interface all | include status
show routing-table all | include AD/VD
```

Resolution Steps

- Step 1: {'Step': '1. Check System Logs', 'Action': 'Run show logbuffer | include ALARM_2637 to identify the root cause'}
- Step 2: {'Step': '2. Verify System Status', 'Action': 'Run show system internal alarm current-alarm to check the alarm status'}
- Step 3: {'Step': '3. Inspect Network Interface', 'Action': 'Run show interface all | include status to verify interface status'}
- Step 4: {'Step': '4. Check Routing Table', 'Action': 'Run show routing-table all | include AD/VD to verify routing table'}
- Step 5: {'Step': '5. Perform Hardware Replacement (if necessary)', 'Action': 'Replace faulty hardware with a spare unit'}
- Step 6: {'Step': '6. Update Software (if necessary)', 'Action': 'Update software to the latest version'}
- Step 7: {'Step': '7. Reconfigure Routing Protocols (if necessary)', 'Action': 'Reconfigure routing protocols to ensure correct operation'}

Post-Check Verification

```
show system internal alarm current-alarm  
show interface all | include status  
show routing-table all | include AD/VD
```