

Huawei PE Router Alarm Resolution SOP

Node: Huawei-PE-Bangalore-KA-71 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_6796

Description

This Standard Operating Procedure (SOP) outlines the steps to diagnose and resolve the ALARM_6796 alarm on Huawei Provider Edge Router, Bangalore KA-71 node.

Potential Root Causes

Cause	Probability
Misconfigured BGP neighbor	High
Interface flap or link issues	Medium
Software or firmware issues	Low

Diagnostic Commands

```
display bgp peer-status
display interface brief
huawei-support-info collect
show version
```

Resolution Steps

- Step 1: {'Step': 'Verify BGP neighbor configuration', 'Action': 'Check BGP neighbor IP address, password, and timer settings using `display bgp peer-status` command.', 'CLI_Command': 'display bgp peer-status'}
- Step 2: {'Step': 'Verify interface status', 'Action': 'Check interface status using `display interface brief` command.', 'CLI_Command': 'display interface brief'}
- Step 3: {'Step': 'Clear BGP session', 'Action': 'Clear BGP session using `clear bgp \*` command.', 'CLI_Command': 'clear bgp *'}
- Step 4: {'Step': 'Verify BGP session status', 'Action': 'Verify BGP session status using `display bgp peer-status` command.', 'CLI_Command': 'display bgp peer-status'}
- Step 5: {'Step': 'Update software or firmware', 'Action': 'Update software or firmware using `huawei-support-info collect` and `show version` command.', 'CLI_Command': 'show version'}

Post-Check Verification

```
display bgp peer-status
display interface brief
```

```
show version
```