

Huawei PE Router Alarm Handling SOP: ALARM_6254

Node: Huawei-PE-Chennai-TN-93 | **Vendor:** Huawei | **Severity:** Major | **Alarm Code:** ALARM_6254

Description

This SOP outlines the steps to handle a Major alarm ALARM_6254 on Huawei PE Router Node ID: Huawei-PE-Chennai-TN-93

Potential Root Causes

Cause	Probability
Invalid or misconfigured BGP Peer	High
Interface or Link issues	Medium
Routing policy issues	Low

Diagnostic Commands

```
display bgp peer all
display interface brief
display routing-policy all
show ip bgp summary
```

Resolution Steps

- Step 1: {'Step': 'Check and verify BGP Peer configuration', 'Action': "Verify BGP Peer configuration using 'display bgp peer all' command", 'CLI_Command': 'display bgp peer '}
- Step 2: {'Step': 'Check and verify interface status', 'Action': "Verify interface status using 'display interface brief' command", 'CLI_Command': 'display interface '}
- Step 3: {'Step': 'Check and verify routing policy', 'Action': "Verify routing policy using 'display routing-policy all' command", 'CLI_Command': 'display routing-policy '}
- Step 4: {'Step': 'Clear BGP sessions if necessary', 'Action': "Clear BGP sessions using 'clear bgp all' command", 'CLI_Command': 'clear bgp all'}

Post-Check Verification

```
display bgp peer all
display interface brief
display routing-policy all
```

```
show ip bgp summary
```