

Huawei Provider Edge Router (PE) SOP: Resolving Alarm ALARM_1957

Node: Huawei-PE-Delhi-NCR-11 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_1957

Description

This SOP outlines the steps to resolve the minor alarm ALARM_1957 on Huawei Provider Edge Router (PE) in Delhi-NCR region.

Potential Root Causes

Cause	Probability
Inconsistent BGP configuration in the PE router	High
Interface flapping in the PE router	Medium
Route reflection in the PE router	Low

Diagnostic Commands

```
display bgp summary
display interface brief
display bgp route-reflection
```

Resolution Steps

- Step 1: {'Step': 'Check and correct BGP configuration in the PE router', 'Action': "Run the command 'display bgp configuration' to verify the BGP configuration and correct any inconsistencies."}
- Step 2: {'Step': 'Verify interface status in the PE router', 'Action': "Run the command 'display interface brief' to verify the interface status and take corrective action if necessary."}
- Step 3: {'Step': 'Disable route reflection in the PE router', 'Action': "Run the command 'undo bgp route-reflection' to disable route reflection and verify the alarm clears."}

Post-Check Verification

```
display bgp summary
display interface brief
display bgp route-reflection
```