

Huawei Provider Edge Router Alarm Resolution SOP: ALARM_2963

Node: Huawei-PE-Delhi-NCR-11 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_2963

Description

This SOP outlines the steps to diagnose and resolve ALARM_2963, a minor alarm on Huawei Provider Edge Router Node ID: Huawei-PE-Delhi-NCR-11.

Potential Root Causes

Cause	Probability
Interface flap due to hardware issue	High
Software bug causing routing table corruption	Medium
Misconfiguration of routing protocols	Low

Diagnostic Commands

```
display this
dis errorinfo
display ip routing-table
display interface status
```

Resolution Steps

- Step 1: {'Step': 'Gather system logs to identify the root cause', 'Action': 'show log collect'}
- Step 2: {'Step': 'Check interface status and logs for any hardware issues', 'Action': 'display interface status && show log interface'}
- Step 3: {'Step': 'Verify routing table and protocols configuration', 'Action': 'display ip routing-table && display this'}
- Step 4: {'Step': 'Run software bug fix if applicable', 'Action': 'apply '}

Post-Check Verification

```
display ip routing-table
display interface status
display errorinfo
```