

Huawei PE Router Alarm Handling SOP - ALARM_7226

Node: Huawei-PE-Delhi-NCR-11 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_7226

Description

This SOP outlines the steps to be taken for handling ALARM_7226 (Warning) on Huawei PE Router Node ID: Huawei-PE-Delhi-NCR-11.

Potential Root Causes

Cause	Probability
High CPU Utilization due to traffic congestion	High
Misconfigured routing policy	Medium
Hardware failure in the PE router	Low

Diagnostic Commands

```
display cpu-statistics
display routing-policy all
display hardware
display fault-alarm
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU utilization levels', 'Action': 'Run command: display cpu-statistics', 'Expected_Output': 'CPU utilization levels within normal range'}
- Step 2: {'Step': '2. Verify routing policy configuration', 'Action': 'Run command: display routing-policy all', 'Expected_Output': 'Valid and correct routing policy configuration'}
- Step 3: {'Step': '3. Inspect hardware status', 'Action': 'Run command: display hardware', 'Expected_Output': 'No hardware failure detected'}
- Step 4: {'Step': '4. Clear any existing alarms', 'Action': 'Run command: reset fault-alarm', 'Expected_Output': 'Alarm cleared'}
- Step 5: {'Step': '5. Reboot the PE router if necessary', 'Action': 'Run command: reboot', 'Expected_Output': 'Router rebooted successfully'}

Post-Check Verification

```
display cpu-statistics
```

```
display routing-policy all  
display hardware  
display fault-alarm
```