

Huawei PE Router Alarm Resolution SOP - ALARM_8725

Node: Huawei-PE-Delhi-NCR-11 | **Vendor:** Huawei | **Severity:** Warning | **Alarm Code:** ALARM_8725

Description

This SOP outlines the procedures to diagnose and resolve the ALARM_8725 on Huawei PE-Delhi-NCR-11 Provider Edge Router.

Potential Root Causes

Cause	Probability
Misconfigured BGP peering	High
Interface flap due to hardware issue	Medium
Routing policy mismatch	Low

Diagnostic Commands

```
display bgp peer
display interface
display routing-policy
```

Resolution Steps

- Step 1: {'Step': 'Verify BGP peering configuration', 'Command': 'display bgp peer'}
- Step 2: {'Step': 'Check interface status and history', 'Command': 'display interface'}
- Step 3: {'Step': 'Verify routing policy configuration', 'Command': 'display routing-policy'}
- Step 4: {'Step': 'Reset BGP peering', 'Command': 'reset bgp peer'}
- Step 5: {'Step': 'Reconfigure interface', 'Command': 'interface reboot'}
- Step 6: {'Step': 'Reapply routing policy', 'Command': 'apply routing-policy'}

Post-Check Verification

```
display bgp peer
display interface
display routing-policy
```