

Huawei Provider Edge Router (Huawei-PE-Kolkata-WB-119) Alarm Handling SOP for ALARM_2734

Node: Huawei-PE-Kolkata-WB-119 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM_2734

Description

Critical alarm on Huawei Provider Edge Router (Huawei-PE-Kolkata-WB-119) triggered due to ALARM_2734. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Hardware failure in the Line Card (LC)	High
Software bug in the Provider Edge Router (Huawei-PE-Kolkata-WB-119)	Medium
High traffic load on the Provider Edge Router (Huawei-PE-Kolkata-WB-119)	Low

Diagnostic Commands

```
display this
debug enable
debug bgp 4
display bgp IPv4 unicast summary
display bgp IPv4 unicast peer-group
```

Resolution Steps

- Step 1: {'Step': 'Power cycle the Line Card (LC)', 'Action': 'Issue the following command: shutdown interface GigabitEthernet 0/0/0/0', 'CLI_Command': 'shutdown interface GigabitEthernet 0/0/0/0'}
- Step 2: {'Step': 'Clear the BGP peer group', 'Action': 'Issue the following command: clear bgp ipv4 ipv4-unicast peer-group', 'CLI_Command': 'clear bgp ipv4 ipv4-unicast peer-group'}
- Step 3: {'Step': 'Verify the hardware health of the Line Card (LC)', 'Action': 'Issue the following command: display hardware health', 'CLI_Command': 'display hardware health'}

Post-Check Verification

```
display bgp ipv4-unicast summary
display bgp ipv4-unicast peer-group
```

display hardware health