

# Huawei PE Router - Alarm 6223 Troubleshooting SOP

**Node:** Huawei-PE-Kolkata-WB-119 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM\_6223

## Description

This SOP outlines the steps to identify, diagnose, and resolve the critical alarm ALARM\_6223 on the Huawei Provider Edge Router PE-Kolkata-WB-119.

## Potential Root Causes

| Cause                   | Probability |
|-------------------------|-------------|
| Hardware Failure        | High        |
| Software Bug            | Medium      |
| Misconfigured Interface | Low         |

## Diagnostic Commands

```
display current-configuration | include interface GigabitEthernet 1/0/0
display interface GigabitEthernet 1/0/0
display system internal alarm all
```

## Resolution Steps

- Step 1: {'Step': 'Verify the interface status', 'Action': 'Run command: display interface GigabitEthernet 1/0/0'}
- Step 2: {'Step': 'Check for hardware failures', 'Action': 'Run command: display system internal alarm all and verify if any hardware related alarm is present'}
- Step 3: {'Step': 'Check for software issues', 'Action': 'Run command: display version and verify if any software update is pending'}
- Step 4: {'Step': 'Check for misconfigured interface', 'Action': 'Run command: display current-configuration | include interface GigabitEthernet 1/0/0 and verify if the interface is properly configured'}
- Step 5: {'Step': 'Reboot the device', 'Action': 'Run command: reboot'}

## Post-Check Verification

```
display interface GigabitEthernet 1/0/0
display system internal alarm all
ping gigabitethernet 1/0/0
```