

SOP for Resolving Huawei-PE-Kolkata-WB-119 Minor Alarm ALARM_7642

Node: Huawei-PE-Kolkata-WB-119 | **Vendor:** Huawei | **Severity:** Minor | **Alarm Code:** ALARM_7642

Description

This SOP outlines the steps to resolve the ALARM_7642 alarm on Huawei-PE-Kolkata-WB-119, a Provider Edge Router.

Potential Root Causes

Cause	Probability
Invalid or misconfigured BGP Peer	High
BGP session down due to network issues	Medium
Software or firmware issues	Low

Diagnostic Commands

```
display bgp peer
display bgp vpnv4 unicast summary
ping
tracert
```

Resolution Steps

- Step 1: {'Step': 'Verify BGP peer status and configuration', 'Action': "Run 'display bgp peer' command to check BGP peer status"}
- Step 2: {'Step': 'Check BGP session status', 'Action': "Run 'display bgp vpnv4 unicast summary' command to check BGP session status"}
- Step 3: {'Step': 'Verify network connectivity', 'Action': "Run 'ping ' command to verify network connectivity"}
- Step 4: {'Step': 'Troubleshoot software or firmware issues', 'Action': "Run 'display version' and 'display diagnose' commands to check for software or firmware issues"}
- Step 5: {'Step': 'Reboot the router', 'Action': "Run 'reload' command to reboot the router"}

Post-Check Verification

```
display bgp peer
display bgp vpnv4 unicast summary
```

ping