

Huawei Provider Edge Router Alarm SOP

Node: Huawei-PE-Mumbai-MH-57 | **Vendor:** Huawei | **Severity:** Critical | **Alarm Code:** ALARM_6784

Description

Alarm Code ALARM_6784 on Huawei-PE-Mumbai-MH-57: Critical

Potential Root Causes

Cause	Probability
High CPU utilization on the control plane	High
Misconfigured routing protocols	Medium
Hardware issues with the line cards	Low

Diagnostic Commands

```
display current-configuration
show routing-table
show cpu-usage
show interface brief
show system internal alarm-alarmcode ALARM_6784
```

Resolution Steps

- Step 1: {'Step': 'Verify the CPU utilization on the control plane', 'Action': "Run 'show cpu-usage' command and check for any anomalies", 'CLI_Command': 'show cpu-usage'}
- Step 2: {'Step': 'Check the routing protocol configuration', 'Action': "Run 'display current-configuration' command and verify the routing protocol configuration", 'CLI_Command': 'display current-configuration'}
- Step 3: {'Step': 'Perform a hardware check on the line cards', 'Action': "Run 'show system internal alarm-alarmcode ALARM_6784' command and check for any hardware issues", 'CLI_Command': 'show system internal alarm-alarmcode ALARM_6784'}
- Step 4: {'Step': 'Reset the line cards if necessary', 'Action': "Run 'reset line-card' command to reset the affected line cards", 'CLI_Command': 'reset line-card'}
- Step 5: {'Step': 'Verify the CPU utilization and routing protocol configuration', 'Action': "Run 'show cpu-usage' and 'show routing-table' commands to verify the fix", 'CLI_Command': 'show cpu-usage; show routing-table'}

Post-Check Verification

```
show cpu-usage
```

```
show routing-table  
show interface brief  
display current-configuration
```