

Huawei Provider Edge Router (PE) - Major Alarm

ALARM_7429 Resolution

Node: Huawei-PE-Mumbai-MH-57 | **Vendor:** Huawei | **Severity:** Major | **Alarm Code:** ALARM_7429

Description

This SOP describes the steps to diagnose and resolve the major alarm ALARM_7429 on the Huawei Provider Edge Router (PE).

Potential Root Causes

Cause	Probability
High CPU utilization due to excessive routing protocols or high volume of traffic	High
Misconfigured BGP peering sessions.	Medium
Software or hardware issues with the router.	Low

Diagnostic Commands

```
display current-configuration
show bgp summary
show cpu-statistics
show process cpu
show system uptime
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU utilization and routing protocol configurations.', 'Action': 'Run "show cpu-statistics" and "display current-configuration" commands to verify CPU utilization and routing protocol configurations.', 'CLI_Command': 'display cpu-statistics | include total'}
- Step 2: {'Step': '2. Verify BGP peering sessions.', 'Action': 'Run "show bgp summary" command to verify BGP peering sessions.', 'CLI_Command': 'show bgp summary'}
- Step 3: {'Step': '3. Check for software or hardware issues.', 'Action': 'Run "show system uptime" and "show process cpu" commands to verify system uptime and process CPU information.', 'CLI_Command': 'show system uptime'}
- Step 4: {'Step': '4. Adjust routing protocol configurations or adjust traffic routing.', 'Action': 'Adjust routing protocol configurations or adjust traffic routing to reduce CPU utilization.', 'CLI_Command': 'config'}
- Step 5: {'Step': '5. Restart the router.', 'Action': 'Restart the router to clear any software or hardware issues.', 'CLI_Command': 'reload'}

Post-Check Verification

```
show cpu-statistics  
show bqp summary  
display current-configuration
```