

Juniper Core Router SOP: ALARM_3833 Minor Alarm Handling

Node: Juniper-Core-Chennai-TN-1 | **Vendor:** Juniper | **Severity:** Minor | **Alarm Code:** ALARM_3833

Description

Minor alarm handling procedure for Juniper Core Router, Node ID: Juniper-Core-Chennai-TN-1, Vendor: Juniper, Role: Core Router, Alarm Code: ALARM_3833, Severity: Minor

Potential Root Causes

Cause	Probability
High CPU Usage	High
Memory Leak	Medium
Software Bug	Low

Diagnostic Commands

```
show system resource
show process cpu
show memory
show system software version
show system configuration
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU Usage', 'Action': "Run 'show system resource' command to check CPU usage. If CPU usage is high, proceed to step 2.", 'CLI_Command': 'show system resource'}
- Step 2: {'Step': '2. Identify and Kill High CPU Process', 'Action': "Run 'show process cpu' command to identify the process consuming high CPU. Kill the process using 'request system kill process' command.", 'CLI_Command': 'request system kill process '}
- Step 3: {'Step': '3. Check Memory Usage', 'Action': "Run 'show memory' command to check memory usage. If memory usage is high, proceed to step 4.", 'CLI_Command': 'show memory'}
- Step 4: {'Step': '4. Clear Memory Cache', 'Action': "Run 'clear system memory' command to clear memory cache.", 'CLI_Command': 'clear system memory'}
- Step 5: {'Step': '5. Update Software Version', 'Action': "Check 'show system software version' command to ensure the software version is up-to-date. If not, update the software version.", 'CLI_Command': 'request system software update'}

Step 6: {'Step': '6. Verify Configuration', 'Action': "Run 'show system configuration' command to verify the configuration. If any issues are found, adjust the configuration.", 'CLI_Command': 'show system configuration'}

Post-Check Verification

```
show system resource
show process cpu
show memory
show system software version
show system configuration
```