

Juniper Core Router SOP - ALARM_7304 (Major)

Node: Juniper-Core-Chennai-TN-1 | **Vendor:** Juniper | **Severity:** Major | **Alarm Code:** ALARM_7304

Description

Alarm Code ALARM_7304 on Node ID Juniper-Core-Chennai-TN-1 indicates a Critical Hardware Fault, requiring immediate attention.

Potential Root Causes

Cause	Probability
Failed Power Supply Unit (PSU)	High
Overheating CPU	Medium
Failed Fan Tray	Low

Diagnostic Commands

```
show system power status
show chassis temperature
show system fan status
```

Resolution Steps

- Step 1: {'Step': 'Power cycle the router', 'CLI_Command': 'request system power-cycle'}
- Step 2: {'Step': 'Replace the failed PSU', 'CLI_Command': 'delete system power-supply '}
- Step 3: {'Step': 'Verify CPU temperature within acceptable range', 'CLI_Command': 'show chassis temperature'}
- Step 4: {'Step': 'Clean the fan tray or replace it if faulty', 'CLI_Command': 'delete system fan-tray '}

Post-Check Verification

```
show system power status
show chassis temperature
show system fan status
```