

Juniper Core Router ALARM_7572 SOP

Node: Juniper-Core-Chennai-TN-1 | **Vendor:** Juniper | **Severity:** Critical | **Alarm Code:** ALARM_7572

Description

Alarm ALARM_7572 on Juniper Core Router Juniper-Core-Chennai-TN-1 is triggered due to a critical issue.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Memory Leak	Medium
Misconfigured Routing Policies	Low

Diagnostic Commands

```
show system resources
show processes cpu
show memory statistics
show routing policy
show configuration
```

Resolution Steps

- Step 1: { 'Step': '1', 'Action': 'Check CPU Utilization', 'CLI_Command': 'show system resources | match cpu' }
- Step 2: { 'Step': '2', 'Action': 'Restart the Router', 'CLI_Command': 'request system restart' }
- Step 3: { 'Step': '3', 'Action': 'Verify Memory Statistics', 'CLI_Command': 'show memory statistics' }
- Step 4: { 'Step': '4', 'Action': 'Reconfigure Routing Policies', 'CLI_Command': 'set routing-policy ' }
- Step 5: { 'Step': '5', 'Action': 'Verify Configuration', 'CLI_Command': 'show configuration' }

Post-Check Verification

```
show system resources | match cpu
show memory statistics
show routing policy
show configuration
```