

Juniper Core Router SOP - ALARM_2840

Node: Juniper-Core-Mumbai-MH-1 | **Vendor:** Juniper | **Severity:** Warning | **Alarm Code:** ALARM_2840

Description

Alarm ALARM_2840 on Node ID: Juniper-Core-Mumbai-MH-1, Vendor: Juniper, Role: Core Router, Severity: Warning

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Misconfigured firewall rules	Medium
Insufficient memory allocation	Low

Diagnostic Commands

```
show system resources
show firewall
show memory
```

Resolution Steps

Step 1: {'Step': '1', 'Action': 'Check CPU utilization and optimize as needed.', 'Commands': ['show system resources', 'request system reboot']}

Step 2: {'Step': '2', 'Action': 'Check and correct misconfigured firewall rules.', 'Commands': ['show firewall', 'edit firewall rule ', 'set firewall rule ']}

Step 3: {'Step': '3', 'Action': 'Verify and adjust memory allocation as required.', 'Commands': ['show memory', 'request system reboot']}

Post-Check Verification

```
show system resources
show firewall
show memory
show system alarm-clear
```