

Juniper Core Router Alarm SOP: ALARM_3695

Node: Juniper-Core-Mumbai-MH-1 | **Vendor:** Juniper | **Severity:** Minor | **Alarm Code:** ALARM_3695

Description

This SOP outlines the steps to diagnose and resolve a minor alarm on the Juniper Core Router, Node ID: Juniper-Core-Mumbai-MH-1. Alarm Code: ALARM_3695, Severity: Minor.

Potential Root Causes

Cause	Probability
Interface Flapping	High
Misconfigured Routing Protocols	Medium
Hardware Issues (Faulty Cards)	Low

Diagnostic Commands

```
show interfaces extensive
show route summary
show bgp summary
show routing-table
show log messages | include ALARM_3695
```

Resolution Steps

- Step 1: {'Step': 'Check Interface Status', 'Action': 'Run command: show interfaces extensive'}
- Step 2: {'Step': 'Verify Routing Protocols Configuration', 'Action': 'Run command: show configuration routing-options'}
- Step 3: {'Step': 'Swap Faulty Cards', 'Action': 'Insert new hardware card and reboot the router'}

Post-Check Verification

```
show interfaces extensive | match ALARM_3695
show route summary | match ALARM_3695
show bgp summary | match ALARM 3695
show routing-table | match ALARM_3695
```