

Juniper Core Router Alarm SOP: ALARM_7006

Node: Juniper-Core-Mumbai-MH-1 | **Vendor:** Juniper | **Severity:** Major | **Alarm Code:** ALARM_7006

Description

Alarm ALARM_7006 on Juniper Core Router Node ID: Juniper-Core-Mumbai-MH-1 indicates a major issue with the device. Upon investigation, this alarm is typically triggered due to a critical hardware or software failure.

Potential Root Causes

Cause	Probability
Critical Hardware Failure	High
Software Configuration Error	Medium
Power Supply Issue	Low

Diagnostic Commands

```
show chassis hardware
show system resources
show system uptime
show log messages | match ALARM_7006
```

Resolution Steps

- Step 1: {'Step': 'Restart the Router', 'Description': 'Issue the command 'request system restart' to restart the router.', 'Command': 'request system restart'}
- Step 2: {'Step': 'Check and Replace Faulty Hardware', 'Description': 'Physically inspect the router and replace any faulty hardware components.', 'Command': 'none'}
- Step 3: {'Step': 'Verify and Correct Software Configuration', 'Description': 'Verify the software configuration and correct any errors.', 'Command': 'show configuration'}

Post-Check Verification

```
show chassis hardware
show system resources
show log messages | match ALARM_7006
```