

# Juniper Core Router SOP: ALARM\_9642 - Major Alarm on Juniper-Core-Mumbai-MH-1

**Node:** Juniper-Core-Mumbai-MH-1 | **Vendor:** Juniper | **Severity:** Major | **Alarm Code:** ALARM\_9642

## Description

This SOP outlines the procedures for diagnosing and resolving the major alarm ALARM\_9642 on the Juniper Core Router, Node ID: Juniper-Core-Mumbai-MH-1.

## Potential Root Causes

| Cause                                             | Probability |
|---------------------------------------------------|-------------|
| High CPU Utilization due to CPU-Intensive Process | High        |
| Misconfigured Routing Policies                    | Medium      |
| Software or Firmware Issues                       | Low         |

## Diagnostic Commands

```
show system processes cpu
show routing policy all
show software version
show firmware version
```

## Resolution Steps

- Step 1: {'Step': '1. Check CPU Utilization and CPU-Intensive Processes', 'Action': "Run the command 'show system processes cpu' to monitor CPU utilization and identify CPU-intensive processes."}
- Step 2: {'Step': '2. Review and Update Routing Policies', 'Action': "Review the routing policies configured on the router using the command 'show routing policy all' and update the policies as necessary."}
- Step 3: {'Step': '3. Update Software or Firmware', 'Action': "Check for any software or firmware updates using the commands 'show software version' and 'show firmware version'. If updates are available, apply them to the router."}
- Step 4: {'Step': '4. Restart the Router', 'Action': 'If none of the above steps resolve the issue, restart the router to ensure a fresh start.'}

## Post-Check Verification

```
show system processes cpu
show routing policy all
```

```
show software version  
show firmware version
```