

Juniper Provider Edge Router Alarm Resolution SOP (ALARM_5482)

Node: Juniper-PE-Chennai-TN-105 | **Vendor:** Juniper | **Severity:** Major | **Alarm Code:** ALARM_5482

Description

Major alarm generated on Juniper PE router Juniper-PE-Chennai-TN-105 due to unexpected loss of adjacency with a peer.

Potential Root Causes

Cause	Probability
High CPU utilization on the router	High
Memory leak in the routing process	Medium
Misconfigured BGP peer group	Low

Diagnostic Commands

```
show system processes
show memory | match -
show bgp summary
show bgp neighbors | match peer-group
```

Resolution Steps

- Step 1: {'Step': '1. Stop unnecessary processes', 'Action': 'kill -9 process-id', 'Note': 'Identify and kill any unnecessary processes consuming CPU resources.'}
- Step 2: {'Step': '2. Clear memory leak', 'Action': 'request system clear memory', 'Note': 'Clear any memory leak in the routing process to prevent further instability.'}
- Step 3: {'Step': '3. Review and correct BGP peer group configuration', 'Action': 'show run | include bgp peer-group', 'Note': 'Verify that the BGP peer group configuration is correct and make any necessary corrections.'}
- Step 4: {'Step': '4. Reload the BGP process', 'Action': 'request pfe reload bgp', 'Note': 'Reload the BGP process to ensure that any changes are applied.'}

Post-Check Verification

```
show bgp summary
show bgp neighbors | match peer-group
```

```
show system processes  
show memory | match -
```