

Juniper Provider Edge Router Alarm SOP for ALARM_9193

Node: Juniper-PE-Chennai-TN-95 | **Vendor:** Juniper | **Severity:** Critical | **Alarm Code:** ALARM_9193

Description

Alarm ALARM_9193 on Juniper-PE-Chennai-TN-95 indicates a critical issue with the router's routing table, possibly due to a BGP session failure or a routing protocol misconfiguration.

Potential Root Causes

Cause	Probability
BGP Session Failure	High
Routing Protocol Misconfiguration	Medium
Hardware or Software Failure	Low

Diagnostic Commands

```
show bgp summary
show bgp neighbors
show routing-table
show configuration routing-options
show system resource-intensive-processes
```

Resolution Steps

Step 1: {'Step': 'Verify BGP session status', 'Command': 'show bgp summary', 'Expected Output': 'BGP session established'}

Step 2: {'Step': 'Check neighbor configuration', 'Command': 'show configuration routing-options neighbor', 'Expected Output': 'Neighbor configuration is correct'}

Step 3: {'Step': 'Restart the BGP process', 'Command': 'request system software restart bgp', 'Expected Output': 'BGP process restarted'}

Step 4: {'Step': 'Verify routing table consistency', 'Command': 'show routing-table', 'Expected Output': 'Routing table is consistent'}

Post-Check Verification

```
show bgp summary
show routing-table
```

```
show system resource-intensive-processes
```