

Node Nokia-Core-Bangalore-KA-1 Core Router Alarm

SOP: ALARM_2755

Node: Nokia-Core-Bangalore-KA-1 | **Vendor:** Nokia | **Severity:** Critical | **Alarm Code:** ALARM_2755

Description

Alarm Code ALARM_2755 - Critical - Triggered on Nokia-Core-Bangalore-KA-1 Core Router

Potential Root Causes

Cause	Probability
Software Defect in Routing Protocol	High
Misconfiguration of Core Router	Medium
Hardware Fault on Core Router	Low

Diagnostic Commands

```
show ip bgp summary
show ip ospf neighbor
show ip routing table
```

Resolution Steps

- Step 1: {'Step': '1. Check Core Router logs for error messages related to ALARM_2755', 'Action': 'show log | include ALARM_2755'}
- Step 2: {'Step': '2. Verify Core Router configuration for correct routing protocol configuration', 'Action': 'show run | include bgp|ospf'}
- Step 3: {'Step': '3. Run diagnostic tests on Core Router hardware', 'Action': 'admin:diagnostic test'}
- Step 4: {'Step': '4. Reboot Core Router if necessary', 'Action': 'reload'}

Post-Check Verification

```
show ip bgp summary
show ip ospf neighbor
show ip routing table
```