

Nokia Core Router Alarm Resolution SOP: ALARM_4129

Node: Nokia-Core-Bangalore-KA-1 | **Vendor:** Nokia | **Severity:** Warning | **Alarm Code:** ALARM_4129

Description

ALARM_4129: Warning - High CPU Utilization on Nokia Core Router Bangalore KA-1

Potential Root Causes

Cause	Probability
High CPU Utilization due to inefficient routing protocols	High
Software bug in the router's OS	Medium
Misconfigured firewall rules	Low

Diagnostic Commands

```
show cpu utilization
show process cpu usage
show routing protocols statistics
show firewall rules
```

Resolution Steps

Step 1: {'Step': '1. Investigate and optimize routing protocols', 'Action': 'Verify routing protocols configuration and optimize as needed'}

Step 2: {'Step': '2. Apply software patch or upgrade', 'Action': 'Check for available software patches or upgrades and apply as necessary'}

Step 3: {'Step': '3. Reconfigure firewall rules', 'Action': 'Re-examine firewall rules and reconfigure as needed'}

Step 4: {'Step': '4. Restart the router', 'Action': 'Restart the router to apply changes'}

Post-Check Verification

```
show cpu utilization
show process cpu usage
show routing protocols statistics
show firewall rules
```