

Nokia Core Router Alarm SOP: ALARM_5512

Node: Nokia-Core-Bangalore-KA-1 | **Vendor:** Nokia | **Severity:** Critical | **Alarm Code:** ALARM_5512

Description

This SOP outlines the steps to diagnose and resolve the ALARM_5512 (Critical) on the Nokia Core Router, Node ID: Nokia-Core-Bangalore-KA-1. The alarm is triggered by a severe issue with the routing protocol.

Potential Root Causes

Cause	Probability
Routing Protocol Misconfiguration	High
Hardware Failure (CPU/Memory)	Medium
Software Bug	Low

Diagnostic Commands

```
show ip bgp summary
show ip routing bgp
show system resources cpu
show system resources memory
```

Resolution Steps

- Step 1: {'Step': '1. Verify routing protocol configuration', 'Action': "Run 'show ip bgp summary' command to check for any misconfigurations"}
- Step 2: {'Step': '2. Check for hardware issues', 'Action': "Run 'show system resources cpu' and 'show system resources memory' commands to check for any hardware failures"}
- Step 3: {'Step': '3. Reset the routing protocol', 'Action': "Run 'clear ip bgp *' command to reset the routing protocol"}
- Step 4: {'Step': '4. Reboot the router (if necessary)', 'Action': "Run 'reboot' command to reboot the router"}

Post-Check Verification

```
show ip bgp summary
show ip routing bgp
```