

Nokia Core Router Alarm Resolution SOP

(ALARM_7616)

Node: Nokia-Core-Bangalore-KA-1 | **Vendor:** Nokia | **Severity:** Major | **Alarm Code:** ALARM_7616

Description

This procedure outlines the steps to diagnose and resolve a Major Alarm (ALARM_7616) on Nokia Core Router Node ID: Nokia-Core-Bangalore-KA-1. The alarm indicates a critical issue that requires immediate attention.

Potential Root Causes

Cause	Probability
High CPU utilization on the Route Processor (RP)	High
Inconsistent routing information in the routing table	Medium
Software or hardware issues with the Core Router	Low

Diagnostic Commands

```
show cpu utilization
show ip bgp summary
show ip route
```

Resolution Steps

Step 1: {'Step': 'Restart the Route Processor (RP)', 'Description': "Execute the command: 'swi restart rp'\r\n", 'Command': 'swi restart rp'}

Step 2: {'Step': 'Clear the routing table', 'Description': "Execute the command: 'clear ip bgp *'\r\n", 'Command': 'clear ip bgp *'}

Step 3: {'Step': 'Upgrade or downgrade the software as needed', 'Description': 'Consult the Nokia documentation and follow the procedures for upgrading or downgrading the software.\r\n', 'Command': 'None'}

Post-Check Verification

```
show cpu utilization
show ip bgp summary
show ip route
```