

Nokia Core Router: ALARM_5297 - Minor Alarm Resolution SOP

Node: Nokia-Core-Bangalore-KA-2 | **Vendor:** Nokia | **Severity:** Minor | **Alarm Code:** ALARM_5297

Description

This SOP outlines the steps to diagnose and resolve ALARM_5297 on Nokia Core Router Node ID: Nokia-Core-Bangalore-KA-2.

Potential Root Causes

Cause	Probability
Hardware Failure of Interface Card	High
Software Issue with Route Reflector	Medium
Misconfiguration of BGP Neighbor	Low

Diagnostic Commands

```
show card detail
show bgp all summary
show bgp all neighbors detail
```

Resolution Steps

- Step 1: {'Step': '1. Replace the faulty Interface Card', 'Description': 'Replace the Interface Card with a new one', 'Commands': ['card replace ', 'show card detail']}
- Step 2: {'Step': '2. Clear the BGP Session', 'Description': 'Clear the BGP session on the Route Reflector', 'Commands': ['clear bgp *', 'show bgp all summary']}
- Step 3: {'Step': '3. Re-configure the BGP Neighbor', 'Description': 'Re-configure the BGP Neighbor on the Core Router', 'Commands': ['configure replace ', 'show bgp all neighbors detail']}

Post-Check Verification

```
show bgp all summary
show card detail
show bgp all neighbors detail
```