

Nokia Core Router - ALARM_4259 SOP

Node: Nokia-Core-Chennai-TN-2 | **Vendor:** Nokia | **Severity:** Critical | **Alarm Code:** ALARM_4259

Description

Alarm ALARM_4259 on Nokia Core Router Chennai TN-2 indicating a critical issue.

Potential Root Causes

Cause	Probability
Software Fault	High
Hardware Failure	Medium
Misconfigured Routing Policy	Low

Diagnostic Commands

```
show alarm summary
show tech-support
show bgp summary
show ip ospf neighbor detail
```

Resolution Steps

- Step 1: {'Step': 'Check System Logs', 'Action': 'show logging history'}
- Step 2: {'Step': 'Verify Routing Policy Configuration', 'Action': 'show run | include policy-map'}
- Step 3: {'Step': 'Reset BGP Session', 'Action': 'clear bgp * soft'}
- Step 4: {'Step': 'Reboot the Router', 'Action': 'reload'}

Post-Check Verification

```
show bgp summary
show ip ospf neighbor detail
show alarm summary
```