

Standard Operating Procedure for Nokia Core Router (Node ID: Nokia-Core-Chennai-TN-2) Alarm

ALARM_9020

Node: Nokia-Core-Chennai-TN-2 | **Vendor:** Nokia | **Severity:** Critical | **Alarm Code:** ALARM_9020

Description

This SOP outlines the steps to diagnose and resolve a Critical Alarm (ALARM_9020) on the Nokia Core Router (Node ID: Nokia-Core-Chennai-TN-2).

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Route Table Overflow	Medium
Misconfigured BGP Neighbor	Low

Diagnostic Commands

```
show cpu utilization
show route summary
show bgp neighbors
show ip bgp summary
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU Utilization', 'Description': 'Verify if CPU utilization is high. If yes, proceed to Step 2.', 'Command': 'show cpu utilization'}
- Step 2: {'Step': '2. Check Route Table Overflow', 'Description': 'Verify if route table is full. If yes, clear the route table or increase the route table size.', 'Command': 'clear ip route *'}
- Step 3: {'Step': '3. Check BGP Neighbor Configuration', 'Description': 'Verify if BGP neighbor is configured correctly. If not, correct the configuration.', 'Command': 'show bgp neighbors'}
- Step 4: {'Step': '4. Restart BGP Process', 'Description': 'Restart the BGP process to clear any issues.', 'Command': 'restart bgp'}

Post-Check Verification

```
show bgp summary
show ip bgp summary
```

```
show cpu utilization
```