

Alarm ALARM_2358 SOP for Nokia Core Router in Delhi NCR-2

Node: Nokia-Core-Delhi-NCR-2 | **Vendor:** Nokia | **Severity:** Major | **Alarm Code:** ALARM_2358

Description

The ALARM_2358 is a Major Severity alarm indicating a significant issue on the Nokia Core Router in Delhi NCR-2. This SOP outlines the diagnostic and resolution steps to troubleshoot and fix the issue.

Potential Root Causes

Cause	Probability
Software defect in the routing protocol	High
Hardware failure in the router	Medium
Misconfiguration of the routing protocol	Low

Diagnostic Commands

```
show ip route
show ip bgp summary
show cpu usage
show memory usage
```

Resolution Steps

- Step 1: {'Step': '1. Check the routing protocol configuration', 'Description': 'Verify that the routing protocol configuration is correct and matches the design requirements.', 'Commands': ['show run | incl router bgp', 'show run | incl router ospf']}
- Step 2: {'Step': '2. Check for software defects', 'Description': 'Verify that the software version is up-to-date and check for any known defects.', 'Commands': ['show version', 'show software version']}
- Step 3: {'Step': '3. Check for hardware failures', 'Description': 'Verify that the hardware is functioning correctly and check for any alarms.', 'Commands': ['show hardware status', 'show alarm history']}
- Step 4: {'Step': '4. Reboot the router', 'Description': 'Reboot the router to reset the configuration and check if the issue resolves.', 'Commands': ['reload']}

Post-Check Verification

```
show ip route
show ip bgp summary
```

```
show cpu usage  
show memory usage
```