

Nokia-Core-Delhi-NCR-2: Critical Alarm SOP - ALARM_3821

Node: Nokia-Core-Delhi-NCR-2 | **Vendor:** Nokia | **Severity:** Critical | **Alarm Code:** ALARM_3821

Description

Critical alarm on Nokia Core Router in Delhi NCR-2 site due to severe network congestion.

Potential Root Causes

Cause	Probability
High CPU utilization due to increased routing protocol updates	High
Misconfigured QoS policy affecting bandwidth allocation	Medium
Hardware failure in the router's line card	Low

Diagnostic Commands

```
show cpu utilization
show ip bqp summary
show policy-map interface
show mpls ldp neighbor
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU utilization and identify the process consuming high CPU', 'Action': 'show cpu utilization', 'Description': 'Verify if CPU utilization is within the threshold limits.'}
- Step 2: {'Step': '2. Verify and adjust QoS policies', 'Action': 'show policy-map interface', 'Description': 'Check if QoS policies are correctly configured and adjust if necessary.'}
- Step 3: {'Step': '3. Perform a hardware inspection and replace the faulty line card if necessary', 'Action': 'show inventory', 'Description': 'Verify the hardware inventory and replace the faulty line card if found.'}

Post-Check Verification

```
show cpu utilization
show ip bqp summary
show policy-map interface
show mpls ldp neighbor
```