

Nokia Core Router ALARM_9135 SOP

Node: Nokia-Core-Delhi-NCR-2 | **Vendor:** Nokia | **Severity:** Critical | **Alarm Code:** ALARM_9135

Description

Alarm ALARM_9135 on Nokia Core Router Delhi-NCR-2 indicates a critical issue with the routing protocol. This SOP outlines the procedures to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Routing protocol configuration issue	High
Hardware failure	Medium
Software bug	Low

Diagnostic Commands

```
show ip bgp summary
show ip bgp neighbors
show ip bgp vpnv4 all summary
show hardware cpu usage
```

Resolution Steps

- Step 1: {'Step': '1. Check routing protocol configuration', 'Action': "Execute the command 'show ip bgp summary' to verify routing protocol configuration.", 'CLI_Command': 'show ip bgp summary'}
- Step 2: {'Step': '2. Verify neighbor relationships', 'Action': "Execute the command 'show ip bgp neighbors' to verify neighbor relationships.", 'CLI_Command': 'show ip bgp neighbors'}
- Step 3: {'Step': '3. Check for hardware issues', 'Action': "Execute the command 'show hardware cpu usage' to verify CPU usage.", 'CLI_Command': 'show hardware cpu usage'}
- Step 4: {'Step': '4. Reset routing protocol', 'Action': "Execute the command 'clear ip bgp *' to reset routing protocol.", 'CLI_Command': 'clear ip bgp *'}
- Step 5: {'Step': '5. Reboot the router', 'Action': "Execute the command 'reload' to reboot the router.", 'CLI_Command': 'reload'}

Post-Check Verification

```
show ip bgp summary
show ip bgp neighbors
```

```
show ip bgp vpnv4 all summary  
show hardware cpu usage
```