

Standard Operating Procedure: Nokia Core Router - ALARM_2203 - Minor Alarm

Node: Nokia-Core-Kolkata-WB-1 | **Vendor:** Nokia | **Severity:** Minor | **Alarm Code:** ALARM_2203

Description

This SOP outlines the steps to diagnose and resolve ALARM_2203 on Nokia Core Router - Nokia-Core-Kolkata-WB-1.

Potential Root Causes

Cause	Probability
Interface flap or misconfiguration	Medium
Software or firmware issues	Low
Hardware issues with interface or port	Low

Diagnostic Commands

```
show interface | include Flapping
show ip int brief
show version
show tech-support
```

Resolution Steps

- Step 1: {'Step': 'Verify interface status', 'Action': 'show interface | include State', 'Description': 'Check if the interface is up or down'}
- Step 2: {'Step': 'Check interface configuration', 'Action': 'show running-config | include ', 'Description': 'Verify if the interface configuration is correct'}
- Step 3: {'Step': 'Reboot the interface', 'Action': 'interface | no shutdown', 'Description': 'Reboot the interface to resolve software or firmware issues'}
- Step 4: {'Step': 'Replace the faulty hardware', 'Action': 'Replace the interface or port with a new one', 'Description': 'Replace the faulty hardware to resolve hardware issues'}

Post-Check Verification

```
show interface | include State
show ip int brief
show version
```