

Nokia Core Router Alarm Response Procedure - ALARM_3773: Node ID: Nokia-Core-Kolkata-WB-1

Node: Nokia-Core-Kolkata-WB-1 | **Vendor:** Nokia | **Severity:** Critical | **Alarm Code:** ALARM_3773

Description

Critical Alarm: ALARM_3773 triggered on Nokia Core Router Node ID: Nokia-Core-Kolkata-WB-1. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Faulty Power Supply Unit (PSU)	High
Cabling issues or misconnections	Medium
Software or firmware issues	Low

Diagnostic Commands

```
show system power
show interfaces status
show run | include PSU
show tech-support
show alarm history ALARM_3773
```

Resolution Steps

- Step 1: {'Step': 'Verify Power Supply Unit (PSU) status', 'Action': "Run 'show system power' command to check PSU status. If faulty, replace PSU and power cycle the router."}
- Step 2: {'Step': 'Inspect cabling and connections', 'Action': 'Visually inspect cabling and connections for any signs of damage or misconnections. Check for loose connections and tighten as necessary.'}
- Step 3: {'Step': 'Run diagnostic tests', 'Action': "Run 'show tech-support' command to collect diagnostic information. Run 'show alarm history ALARM_3773' to check for any historical records of the alarm."}
- Step 4: {'Step': 'Reboot the router', 'Action': "Run 'reboot' command to reboot the router and clear any stuck routes or sessions."}

Post-Check Verification

```
show system power
show interfaces status
```

```
show run | include PSU
show tech-support
show alarm history ALARM_3773
```