

Standard Operating Procedure for Nokia Core Router Alarm ALARM_8724

Node: Nokia-Core-Kolkata-WB-1 | **Vendor:** Nokia | **Severity:** Warning | **Alarm Code:** ALARM_8724

Description

Alarm ALARM_8724 on Nokia Core Router Node ID: Nokia-Core-Kolkata-WB-1 indicates a warning condition. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
High CPU Utilization due to Routing Protocol Flap	High
Misconfigured Policy-Based Routing (PBR) Rules	Medium
Software Bug or Defect	Low

Diagnostic Commands

```
show system resource cpu utilization
show routing protocols all
show ip policy routing all
show debug
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU Utilization', 'Action': 'Run the show system resource cpu utilization command to monitor CPU utilization. If utilization is high, proceed to step 2.'}
- Step 2: {'Step': '2. Identify and Resolve Routing Protocol Flap', 'Action': 'Run the show routing protocols all command to identify the source of the flap. Update the routing configuration to prevent future flaps. Run the commit command to save changes.'}
- Step 3: {'Step': '3. Review PBR Rules', 'Action': 'Run the show ip policy routing all command to review PBR rules. Update or delete misconfigured rules. Run the commit command to save changes.'}
- Step 4: {'Step': '4. Check for Software Bug or Defect', 'Action': 'Contact Nokia Support to check for any known software bugs or defects. Apply any recommended software patches or updates.'}

Post-Check Verification

```
show system resource cpu utilization
show routing protocols all
```

```
show ip policy routing all  
show system status
```