

Nokia Core Router - ALARM_3508 - CPU Threshold Exceeded (Warning)

Node: Nokia-Core-Kolkata-WB-2 | **Vendor:** Nokia | **Severity:** Warning | **Alarm Code:** ALARM_3508

Description

This alarm is triggered when the CPU usage exceeds the configured threshold on the Nokia Core Router.

Potential Root Causes

Cause	Probability
High CPU usage due to excessive packet processing	High
Insufficient CPU resources due to under-provisioning	Medium
Malfunctioning or faulty CPU hardware	Low

Diagnostic Commands

```
show cpu usage
show cpu threshold
show system info
show hardware status
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU usage and threshold values', 'Action': "Run 'show cpu usage' and 'show cpu threshold' commands", 'Description': 'Verify if CPU usage exceeds the threshold value'}
- Step 2: {'Step': '2. Adjust CPU threshold value', 'Action': "Use 'set cpu threshold' command to adjust the value", 'Description': 'Set a higher threshold value to avoid false alarms'}
- Step 3: {'Step': '3. Upgrade CPU resources (if under-provisioned)', 'Action': 'Consult with vendor and perform hardware upgrades', 'Description': 'Ensure sufficient CPU resources to handle traffic'}
- Step 4: {'Step': '4. Replace faulty CPU hardware (if malfunctioning)', 'Action': 'RMA (Return Merchandise Authorization) faulty hardware', 'Description': 'Replace faulty hardware with a new one'}

Post-Check Verification

```
show cpu usage
show cpu threshold
show system info
```

```
show hardware status
```