

Nokia Core Router SOP: Alarm Code ALARM_4082

Node: Nokia-Core-Kolkata-WB-2 | **Vendor:** Nokia | **Severity:** Major | **Alarm Code:** ALARM_4082

Description

This SOP outlines the steps to diagnose and resolve the Major Alarm ALARM_4082 on Nokia Core Router Node ID: Nokia-Core-Kolkata-WB-2.

Potential Root Causes

Cause	Probability
High CPU Utilization due to Routing Protocol Flap	High
Memory Leak due to Software Bug	Medium
Network Congestion due to High Traffic Volume	Low

Diagnostic Commands

```
show route all
show ip bgp summary
show memory statistics
show cpu utilization
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU Utilization', 'Action': 'Execute command: show cpu utilization', 'CLI_Command': 'show cpu utilization'}
- Step 2: {'Step': '2. Check Memory Statistics', 'Action': 'Execute command: show memory statistics', 'CLI_Command': 'show memory statistics'}
- Step 3: {'Step': '3. Verify Routing Protocol Configuration', 'Action': 'Verify configuration using command: show route all', 'CLI_Command': 'show route all'}
- Step 4: {'Step': '4. Restart Routing Protocol Process', 'Action': 'Execute command: restart routing protocol process', 'CLI_Command': 'restart routing protocol process'}
- Step 5: {'Step': '5. Monitor System for Further Issues', 'Action': 'Monitor system logs and performance metrics for further issues', 'CLI_Command': ''}

Post-Check Verification

```
show cpu utilization
show memory statistics
```

```
show route all  
show ip bgp summary
```