

Nokia Core Router Alarm Response SOP:

ALARM_8439

Node: Nokia-Core-Kolkata-WB-2 | **Vendor:** Nokia | **Severity:** Critical | **Alarm Code:** ALARM_8439

Description

Alarm ALARM_8439 on Nokia Core Router Node ID Nokia-Core-Kolkata-WB-2 indicates a critical issue. This SOP outlines steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Hardware Failure: Interface Card Fault	High
Software Bug: Routing Protocol Issue	Medium
Misconfiguration: Interface Settings	Low

Diagnostic Commands

```
show interface detail
show routing protocol status
show configuration interface
```

Resolution Steps

- Step 1: {'Step': '1. Power cycle the interface card', 'Action': "Use the command 'swic shutdown' and then 'swic no shutdown' to power cycle the interface card."}
- Step 2: {'Step': '2. Verify interface settings', 'Action': "Use the command 'show configuration interface ' to verify interface settings. Make any necessary adjustments."}
- Step 3: {'Step': '3. Clear routing protocol cache', 'Action': "Use the command 'clear ip routing ' to clear the routing protocol cache."}
- Step 4: {'Step': '4. Verify routing protocol status', 'Action': "Use the command 'show routing protocol status' to verify routing protocol status."}
- Step 5: {'Step': '5. Replace hardware (if hardware failure is confirmed)', 'Action': 'Contact the hardware team for assistance in replacing the faulty interface card.'}

Post-Check Verification

```
show interface detail
show routing protocol status
```

```
show configuration interface
```