

Nokia Core Router Alarm SOP (ALARM_1319)

Node: Nokia-Core-Mumbai-MH-2 | **Vendor:** Nokia | **Severity:** Minor | **Alarm Code:** ALARM_1319

Description

Alarm Code: ALARM_1319, Severity: Minor, Node ID: Nokia-Core-Mumbai-MH-2, Vendor: Nokia, Role: Core Router

Potential Root Causes

Cause	Probability
Misconfigured Routing Policy	High
Hardware Fault in Line Card	Medium
Software Bug in Router OS	Low

Diagnostic Commands

```
show routing-policy all
show hardware line-card status
show software os version
```

Resolution Steps

- Step 1: {'Step': 'Verify and correct routing policy', 'Action': "Use 'show routing-policy all' command to identify misconfigured policy. Correct the policy using 'configure routing-policy' command."}
- Step 2: {'Step': 'Replace faulty line card', 'Action': "Use 'show hardware line-card status' command to identify faulty line card. Replace the faulty line card with a new one."}
- Step 3: {'Step': 'Apply software patch', 'Action': "Use 'show software os version' command to identify software version. Apply the latest software patch using 'apply software patch' command."}

Post-Check Verification

```
show routing-policy all
show hardware line-card status
show software os version
```