

Troubleshooting Nokia Core Router ALARM_7945 in Mumbai, India

Node: Nokia-Core-Mumbai-MH-2 | **Vendor:** Nokia | **Severity:** Minor | **Alarm Code:** ALARM_7945

Description

Minor alarm indicating potential issue with packet processing on Nokia Core Router in Mumbai, India

Potential Root Causes

Cause	Probability
High CPU utilization due to excessive packet processing	High
Misconfigured packet classification rules	Medium
Software or hardware issue with packet processing card	Low

Diagnostic Commands

```
show cpu usage
show packet classification rules
show card status
show log messages | include ALARM_7945
```

Resolution Steps

Step 1: {'Step': 'Verify CPU utilization and identify processes causing high utilization', 'Action': 'Run show cpu usage and analyze output'}

Step 2: {'Step': 'Check and correct packet classification rules', 'Action': 'Run show packet classification rules and update rules as necessary'}

Step 3: {'Step': 'Replace or reboot packet processing card if necessary', 'Action': 'Run show card status and replace or reboot card as necessary'}

Step 4: {'Step': 'Reset or reload software if necessary', 'Action': 'Run reload or reset software as necessary'}

Post-Check Verification

```
show cpu usage
show packet classification rules
show card status
show log messages | include ALARM_7945
```