

Nokia Provider Edge Router SOP for Alarm Code ALARM_2288

Node: Nokia-PE-Chennai-TN-100 | **Vendor:** Nokia | **Severity:** Major | **Alarm Code:** ALARM_2288

Description

This SOP outlines the steps to diagnose and resolve the ALARM_2288 issue on the Nokia Provider Edge Router located in Chennai, TN, Node ID: Nokia-PE-Chennai-TN-100.

Potential Root Causes

Cause	Probability
Hardware failure in the provider edge router	High
Software bug in the provider edge router's routing protocol	Medium
Misconfigured routing policy on the provider edge router	Low

Diagnostic Commands

```
show logging | inc ALARM_2288
show alarm-history
show routing-policy
show bgp summary
```

Resolution Steps

- Step 1: {'Step': '1. Check the system log for any error messages related to the ALARM_2288', 'Action': "Run the command 'show logging | inc ALARM_2288'"}
Step 2: {'Step': '2. Check the alarm history for any related alarms', 'Action': "Run the command 'show alarm-history'"}
Step 3: {'Step': '3. Verify the routing policy configuration', 'Action': "Run the command 'show routing-policy'"}
Step 4: {'Step': '4. Verify the BGP configuration and neighbor relationships', 'Action': "Run the command 'show bgp summary'"}
Step 5: {'Step': '5. Check for any hardware issues on the provider edge router', 'Action': "Run the command 'show hardware | inc Critical'"}
Step 6: {'Step': '6', 'Action': 'If a hardware issue is found, contact the hardware vendor for assistance.'}
Step 7: {'Step': '7. Check for any software issues on the provider edge router', 'Action': "Run the command 'show software | inc Critical'"}

Step 8: {'Step': 8, 'Action': 'If a software issue is found, contact the software vendor for assistance.'}

Step 9: {'Step': 9, 'Action': 'If none of the above steps resolve the issue, contact the network operations center for further assistance.'}

Post-Check Verification

```
show logging | inc ALARM_2288
show alarm-history
show routing-policy
show bgp summary
```