

Nokia Provider Edge Router - Major Alarm (ALARM_4789) Resolution SOP

Node: Nokia-PE-Chennai-TN-100 | **Vendor:** Nokia | **Severity:** Major | **Alarm Code:** ALARM_4789

Description

This Standard Operating Procedure (SOP) outlines the steps to resolve a Major alarm on the Nokia Provider Edge Router (Node ID: Nokia-PE-Chennai-TN-100) triggered by Alarm Code: ALARM_4789.

Potential Root Causes

Cause	Probability
Physical Interface Failure	High
Software Bug	Medium
Misconfiguration	Low

Diagnostic Commands

```
show interface | include Error
debug bgp | include Error
show bgp | include Error
```

Resolution Steps

Step 1: {'Step': 'Verify Physical Interface Status', 'Action': "Use the command 'show interface | include Error' to check for any error messages related to the interface.", 'CLI_Command': 'show interface | include Error'}

Step 2: {'Step': 'Check Software Version', 'Action': 'Verify if the software version is up-to-date and there are any known bugs related to the alarm code.', 'CLI_Command': 'show version'}

Step 3: {'Step': 'Check Configuration', 'Action': 'Verify the configuration of the interface and the BGP peer.', 'CLI_Command': 'show bgp | include Peer'}

Step 4: {'Step': 'Reset the Interface', 'Action': 'Reset the physical interface to see if it resolves the issue.', 'CLI_Command': 'interface , shutdown, no shutdown'}

Post-Check Verification

```
show interface | include Error
show bgp | include Error
show bgp | include Established
```