

Nokia PE Router Minor Alarm: ALARM_9236

Resolution SOP

Node: Nokia-PE-Chennai-TN-100 | **Vendor:** Nokia | **Severity:** Minor | **Alarm Code:** ALARM_9236

Description

This SOP outlines the steps to diagnose and resolve the minor alarm ALARM_9236 on the Nokia Provider Edge Router located at Chennai, TN-100.

Potential Root Causes

Cause	Probability
High CPU utilization on the router	High
Memory leak in the system	Medium
Misconfigured routing policy	Low

Diagnostic Commands

```
show cpu utilization
show memory utilization
show routing policy
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU utilization', 'Action': "Run the command 'show cpu utilization' to verify the CPU usage.", 'CLI_Command': 'show cpu utilization'}
- Step 2: {'Step': '2. Check Memory utilization', 'Action': "Run the command 'show memory utilization' to verify the memory usage.", 'CLI_Command': 'show memory utilization'}
- Step 3: {'Step': '3. Check routing policy', 'Action': "Run the command 'show routing policy' to verify the routing policy configuration.", 'CLI_Command': 'show routing policy'}
- Step 4: {'Step': '4. Reset the router', 'Action': 'If the issue persists, reset the router to its default state.', 'CLI_Command': 'reset system'}

Post-Check Verification

```
show cpu utilization
show memory utilization
show routing policy
```